

COMMONWEALTH OF MASSACHUSETTS EXECUTIVE OFFICE OF ENVIRONMENTAL AFFAIRS

DEPARTMENT OF ENVIRONMENTAL PROTECTION ONE WINTER STREET, BOSTON MA 02108 (617) 292-5500

RECEIVED JUL 19 1999

TRUDY COXE Secretary

ARGEO PAUL CELLUCCI Governor

DAVID B. STRUHS Commissioner

SUBSURFACE SEWAGE DISPOSAL SYSTEM INSPECTION FORM PART A CERTIFICATION

Property Address: ZY TRILLIUM WAY AMHERST, MA. CIOG'2 Name of Owner JON + BECKY HURWITE of Owner: ZY TRILLIUM WAY. Address of Owner: A MHERST, MA Date of Inspection: 7/16/17 01002 Name of Inspector: (Please Print) Alan E. Weiss, R.S. I am a DEP approved system inspector pursuant to Section 15.340 of Title 5 (310 CMR 15.000) Company Name: Cold Spring Environmental, Inc. Mailing Address: 350 Old Enfield Rd., Belchertown, MA 01007 Telephone Number: 413-323-5957

CERTIFICATION STATEMENT

I certify that I have personally inspected the sewage disposal system at this address and that the information reported below is true, accurate and complete as of the time of inspection. The inspection was performed based on my training and experie per function and H OF maintenance of on-site sewage disposal systems. The system:

/	Passes	1
	Conditionally Passes	[/5
	Needs Further Evaluation By the Local Approving Authority	
	Fails	1 1
Inspector's Signature:	Ab Date:	7/16/99


The System Inspector shall submit a copy of this inspection report to the Approving Authority (Board of Health or DEP) within thirty (30) days of completing this inspection. If the system is a shared system or has a design flow of 10,000 gpd or greater, the inspector and the system owner shall submit the report to the appropriate regional office of the Department of Environmental Protection. The original should be sent to the system owner and copies sent to the buyer, if applicable, and the approving authority.

NOTES AND COMMENTS

NEW SYSTEM IN SEPT. 1996

revised 9/2/98





Property Address: 24 TRILLIUM WAT Owner: HURWITZ Date of Inspection: 7/16/99

INSPECTION SUMMARY: Check A, B, C, or D:

A. SYSTEM PASSES:

I have not found any information which indicates that any of the failure conditions described in 310 CMR 15.303 exist. Any failure criteria not evaluated are indicated below.

COMMENTS:

B. SYSTEM CONDITIONALLY PASSES:

One or more system components as described in the "Conditional Pass" section need to be replaced or repaired. The system, upon completion of the replacement or repair, as approved by the Board of Health, will pass.

Indicate yes, no, or not determined (Y, N, or ND). Describe basis of determination in all instances. If "not determined", explain why not.

The septic tank is metal, unless the owner or operator has provided the system inspector with a copy of a Certificate of Compliance (attached) indicating that the tank was installed within twenty (20) years prior to the date of the inspection; or the septic tank, whether or not metal, is cracked, structurally unsound, shows substantial infiltration or exfiltration, or tank failure is imminent. The system will pass inspection if the existing septic tank is replaced with a complying septic tank as approved by the Board of Health.

Sewage backup or breakout or high static water level observed in the distribution box is due to broken or obstructed pipe(s) or due to a broken, settled or uneven distribution box. The system will pass inspection if (with approval of the Board of Health).



broken pipe(s) are replaced

obstruction is removed


distribution box is levelled or replaced

The system required pumping more than four times a year due to broken or obstructed pipe(s). The system will pass inspection if (with approval of the Board of Health):

broken pipe(s) are replaced

obstruction is removed

..



24 TZILLIUM WAY

Property Address: 2/16/99 Owner: Hulwite Date of Inspection:


C. FURTHER EVALUATION IS REQUIRED BY THE BOARD OF HEALTH:

Conditions exist which require further evaluation by the Board of Health in order to determine if the system is failing to protect the public health, safety and the environment.

- 1) SYSTEM WILL PASS UNLESS BOARD OF HEALTH DETERMINES IN ACCORDANCE WITH 310 CMR 15.303 (1)(b) THAT THE SYSTEM IS NOT FUNCTIONING IN A MANNER WHICH WILL PROTECT THE PUBLIC HEALTH AND SAFETY AND THE ENVIRONMENT:
 - Cesspool or privy is within 50 feet of surface water
 - Cesspool or privy is within 50 feet of a bordering vegetated wetland or a salt marsh.

- 2) SYSTEM WILL FAIL UNLESS THE BOARD OF HEALTH (AND PUBLIC WATER SUPPLIER, IF ANY) DETERMINES THAT THE SYSTEM IS FUNCTIONING IN A MANNER THAT PROTECTS THE PUBLIC HEALTH AND SAFETY AND THE ENVIRONMENT:
 - The system has a septic tank and soil absorption system (SAS) and the SAS is within 100 feet of a surface water supply or tributary to a surface water supply.
 - ____ The system has a septic tank and soil absorption system and the SAS is within a Zone I of a public water supply well.
 - The system has a septic tank and soil absorption system and the SAS is within 50 feet of a private water supply well.
 - The system has a septic tank and soil absorption system and the SAS is less than 100 feet but 50 feet or more from a private water supply well, unless a well water analysis for coliform bacteria and volatile organic compounds indicates that the well is free from pollution from that facility and the presence of ammonia nitrogen and nitrate nitrogen is equal to or less than 5 ppm. Method used to determine distance (approximation not valid).

3) OTHER



Property Address: 24 TRILLIUM WAY Owner: HURWITZ Date of Inspection: 7/16/99

D. SYSTEM FAILS:

You must indicate either "Yes" or "No" to each of the following:

		ination is identified below. The Board of Health should be contacted to determine what will be necessary to correct the failure.
Yes	No	
		Backup of sewage into facility or system component due to an overloaded or clegged SAS or cesspool.
·		Discharge or ponding of effluent to the surface of the ground or surface waters due to an overloaded or clogged SAS or cesspool.
		Static liquid level in the distribution box above outlet invert due to an overloaded or clogged SAS or cesspool.
		Liquid depth in cesspool is less than 6" below invert or available volume is less than 1/2 day flow.
		Required pumping more than 4 times in the last year <u>NOT</u> due to clogged or obstructed pipe(s). Number of times pumped
_	_	Any portion of the Soil Absorption System, cesspool or privy is below the high groundwater elevation.
		Any portion of a cesspool or privy is within 100 feet of a surface water supply or tributary to a surface water supply.
		Any portion of a cesspool or privy is within a Zone I of a public well.
		Any portion of a cesspool or privy is within 50 feet of a private water supply well.
	• <u>••••</u> ••	Any portion of a cesspool or privy is less-than 100 feet but greater than 50 feet from a private water supply well with no acceptable water quality analysis. If the well has been analyzed to be acceptable, attach copy of well water analysis for +coliform bacteria, volatile organic-compounds, ammonia nitrogen and nitrate nitrogen.


E. LARGE SYSTEM FAILS:

You must indicate either "Yes" or "No" to each of the following:

The following criteria apply to large systems in addition to the criteria above:

The system serves a facility with a design flow of 10,000 gpd or greater (Large System) and the system is a significant threat to public health and safety and the environment because one or more of the following conditions exist:

The owner or operator of any such system shall upgrade the system in accordance with 310 CMR 15.304(2). Please consult the local regional office of the Department for further information.




SUBSURFACE SEWAGE DISPOSAL SYSTEM INSPECTION FORM PART B CHECKLIST

Property Address: Z4 TRICLIM WAY Owner: HURWITT Date of Inspection: 7 116/99

Check if the following have been done: You must indicate either "Yes" or "No" as to each of the following:

No Pumping information was provided by the owner, occupant, or Board of Health. None of the system components have been pumped for at least two weeks and the system has been receiving menual flow rates during that period. Large volumes of water have not been introduced into the system recently or as part of this inspection. As built plans have been obtained and examined. Note if they are not available with N/A. The facility or dwelling was inspected for signs of sewage back-up. The system does not receive non-sanitary or industrial waste flow. The site was inspected for signs of breakout. All system components, excluding the Soil Absorption System, have been located on the site. The septic tank manholes were uncovered, opened, and the interior of the septic tank was inspected for condition of baffles or tees, material of construction, dimensions, depth of liquid, depth of sludge, depth of scum. The size and location of the Soil Absorption System on the site has been determined based on: Existing information. For example, Plan at B.O.H. Determined in the field (if any of the failure criteria related to Part C is at issue, approximation of distance is unacceptable) [15.302(3)(b)] The facility owner (and occupants, if different from owner) were provided with information on the proper maintenance of SubSurface Disposal Systems.

..



Property Address: 24 TRILLIUM WAY Owner: HURW. TR Date of Inspection: 7/16/99

FLOW CONDITIONS

RESIDENTIAL:
Design flow: 550 g.p.d./bedroom.
Number of bedrooms (design): 5 Number of bedrooms (actual):
Total DESIGN flow 703
Number of current residents: 5
Garbage grinder (yes or no): Y & Mat Recommended. Not Removed in 1996
Garbage grinder (yes or no): \underline{Y} + ruch Re(cmmended, Not Removed); is 1996 Laundry (separate system) (yes or no): \underline{N} ; If yes, separate inspection required
Laundry system inspected (vesor no)
Seasonal use (yes or no): N
Water meter readings, if available (last two year's usage (gpd): 🛛 🕅 A
Sump Pump (yes or no): <u>N</u>
Last date of occupancy: Current

COMMERCIAL/INDUSTR	
Type of establishment:	NIA
Design flow:	gpd (Based on 15.203)
Basis of design flow	
Grease trap present: (yes	s or no)
Industrial Waste Holding	Tank present: (yes or no)
Non-sanitary waste disch	narged to the Title 5 system: (yes or no)
Water meter readings, if	available:
Last date of occupancy:_	

OTHER:	(Describe)	
--------	------------	--

Last date of occupancy:_

GENERAL INFORMATION

PUMPING RECORDS and source of information: <u>Yes</u>, <u>New</u> in 1996 System pumped as part of inspection: (ve) or no)____ If yes, volume pumped: 1500 gallons Reason for pumping. Time .


т	Y	P	E	OF	S	YS	Т	EM	
				-					

- Septic tank/distribution box/soil absorption system
- Single cesspool Overflow cesspeol
- Privy
- Shared system (yes or no) (if yes, attach previous inspection records, if any) I/A Technology etc. Attach copy of up to date operation and maintenance contract
- Tight Tank Copy of DEP Approval


Other

APPROXIMATE AGE of all components, date installed (if known) and source of information:

Sewage odors detected when arriving at the site: (yes or no) N



Bronoth Address: 74 TANA LAN LAN	
Property Address: ZY TRULIUM WAY Owner: HUDWITI	
Owner: Hurwitt Date of Inspection: 7/16/19	
BUILDING SEWER:	
(Locate on site plan)	
Depth below grade:	
Material of construction: cast iron40 PVC other (explain)	
Distance from private water supply well or suction line 10 +	
Diameter _ 4 " ϕ	
Comments: (condition of joints, venting, evidence of leakage, etc.)	
SEPTIC TANK:	
(locate on site plan)	
Depth below grade: 12	
Material of construction: Concrete metal Fiberglass Polyethylene other(explain)	
New in 1996	
f tank is metal, list age Is age confirmed by Certificate of Compliance (Yes/No)	
Dimensions: 10.5' × 4.5' × 4.5'	
Sludge depth: 6"	
Distance from top of sludge to bottom of outlet tee or baffle: 43°	
Scum thickness: 2"	
Distance from top of scum to top of outlet tee or baffle: 12 "	
Distance from bottom of scum to bottom of outlet tee or baffle: 41	
tow dimensions were determined: Measured.	
Comments:	
recommendation for pumping, condition of inlet and outlet tees or baffles, depth of liquid level in relation to c	utlet invert, structural integrity,
evidence of leakage, etc.) OK. CONDITION	
GREASE TRAP: NA	
locate on site plan)	
Depth below grade:	
Naterial of construction:concretemetalFiberglassPolyethyleneother(explain)	
Dimensions:	
Soum thickness:	
Distance from top of soum to top of outlet tee or baffle:	
Distance from bottom of scum to bottom of outlet tee or baffle:	
Date of last pumping:	
Comments:	
recommendation for pumping, condition of inlet and outlet tees or baffles, depth of liquid level in relation to o	utlet invert structural integrity
vidence of leakage, etc.)	



Property Address: ZY TRILLIAM WAY Owner: HURWITE Date of Inspection: 7/16/84

TIGHT OR HOLDING TANK: \mathcal{H}/\mathcal{A} (Tank must be pumped prior to, or at time of, inspection) (locate on site plan)

Depth below grade:____ Material of construction: ____concrete ___metal __Fiberglass __Polyethylene ___other(explain)

Dimensions:______ gallons
Capacity:______ gallons
Design flow:______ gallons/day
Alarm present_____
Alarm level: ______ Alarm in working order: Yes ____ No___
Date of previous pumping: ______
Comments:
(condition of inlet tee, condition of alarm and float switches, etc.)

DISTRIBUTION BOX:

(locate on site plan)


Depth of liquid level above outlet invert: at invert

Comments: (note if level and distribution is equal, evidence of solids carryover, evidence of leakage into or out of box, etc.) <u>Cood</u> <u>Condition</u>

PUMP CHAMBER: NA (locate on site plan)

Pumps in working order: (Yes or No)_____ Alarms in working order (Yes or No)_____ Comments: (note condition of pump chamber, condition of pumps and appurtenances, etc.)

revised 9/2/98



Property Address: 24 TRILL IUM WAY HUZWITZ Owner: Date of Inspection: 7 114 199

SOIL ABSORPTION SYSTEM (SAS): (locate on site plan, if possible; excavation not required, location may be approximated by non-intrusive methods)

If not located, explain:

Түре:	leaching pits, number: leaching chambers, number: leaching galleries, number: leaching trenches, number, length: 2 leaching fields, number, dimensions: overflow cesspool, number: Alternative system: Name of Technology:	<u>at 82</u>	ft. Long	x 3 ^{ft}	W.DE X	2 H DEEP.
Commo	ntc.					

Comments:

(note condition o	of soil, signs of hydr	aulic failure, level of pondin	ng, damp soil, condition of vegetation, etc.)
OL, NO S.	in of failure.	, 6 cool flow.	

CESSPOOLS: NA

(locate on site plan)

Number and configuration:	
Depth-top of liquid to inlet invert:	
Depth of solids layer:	
Depth of scum layer:	
Dimensions of cesspool:	
Materials of construction:	
Indication of groundwater:	
inflow (cesspool must be pumped as part of insp	pection)

Comments:

(note condition of soil, signs of hydraulic failure, level of ponding, condition of vegetation, etc.)

PRIVY: NA (locate on site plan)

Materials of construction:


Depth of solids: Comments:

(note condition of soil, signs of hydraulic failure, level of ponding, condition of vegetation, etc.)

.....

revised 9/2/98


Dimensions:




Property Address: Z4 TRULIUM WAY Owner: HURWITE Date of Inspection: 7/16/99

SKETCH OF SEWAGE DISPOSAL SYSTEM:

include ties to at least two permanent reference landmarks or benchmarks locate all wells within 100' (Locate where public water supply comes into house)





Propert Owner:	Address: 24 TRILLIUM WAY fullwite			
Date of	Inspection: 7/16/99			
NRCS	Report name			
	Soil Type			
	Typical depth to groundwater			
USGS	Date website visited			
	Observation Wells checked			
	Groundwater depth: Shallow	Moderate	Deep	
SITE EX				
SHELA	Surface water			
	Check Cellar			
	Shallow wells			
Estimate	ed Depth to Groundwater $\underline{\mathfrak{l}+}$ Feet	(oct. 95. perc + de	epholic.	
Please i	ndicate all the methods used to detern	nine High Groundwater Eleva	tion:	
10	otained from Design Plans on record			
0	oserved Site (Abutting property, obser	vation hole, basement sump	etc.)	
D	etermined from local conditions			
V ci	necked with local Board of health			
CI	necked FEMA Maps			
CI	necked pumping records			
Cł	necked local excavators, installers			
U:	ed USGS Data			
Describe	how you established the High Group	ndwatar Flevation (Must be c	ompleted	

BASED ON SITE REVIEW AND A95 DEEP HUE TEST.

