

## COLD SPRING ENVIRONMENTAL CONSULTANTS INC.

- 21E Site Investigations
- Subsurface Investigations
- Pollution Remediation
- LSP on Staff
- · Forensic Septic Investigations

- · Percolation Tests
- · Septic Designs
- Regulatory Compliance
- · Recycling and Solid Waste
- Second Opinions

October 19, 2010

Gary Courtmanche, Sanitarian Amherst Health Department

RE:Sewer/septic Pipe Repair Installation Inspection 335 Market Hill Road (Whirlwind Kennel)

On this date, the writer inspected the minor repair of a crushed pipe exiting the kennel and leading to a septic tank. The writer found the installation to be complete (except for completion of cover material and final fill) and in compliance with our plans and 310 CMR 15.000. The installer representative (Karls Excavation) & My inspection noted that the pipe was installed properly, in accordance with the state regulations and our plans. The contractor was requested to have sufficient cover soil on site and properly cover the system according to our plans and may backfill the system and copy of this inspection to Health Department representatives.

Sincerely,


Cold Spring Environmental Consultants, Inc.

Alan E. Weiss, M.S., L.S.P. President Principal Hydrogeologist Licensed Site Professional #6442 Registered Sanitarian #933

Cc: Steve Kanieczny, Karls Excavating Cold Spring Environmental 350 Old Enfield Road Beichertown, Ma. 01007

413-323-5957, phone 413-323-4916, fax

Photos & Field Sketch Attached



						,	
							•
		S	E				



Repaired line to tank at Whirlwind Kennels Market Hill Road Amherst, MA 10.19.2010



Repaired line to (inlet tee) at S. tank at Whirlwind Kennels 435 Market Hill Road Amherst, MA 10.19.2010

\*