

74 WIZO FLOWER DRIVE





**COLD SPRING ENVIRONMENTAL  
CONSULTANTS INC.**

- 2IE Site Investigations
- Subsurface Investigations
- Pollution Remediation
- LSP on Staff
- Forensic Septic Investigations

- Percolation Tests
- Septic Designs
- Regulatory Compliance
- Recycling and Solid Waste
- Second Opinions

received  
10-28-08

October 27, 2008


**Amherst Board of Health**

RE:Septic System Repair Installation Inspection  
# (74) Wildflower Lane (Poli Residence)

On this date, the writer inspected the installation of a **Septic Tank and Leach Field**. The writer found the installation to be complete (except for completion of cover material and final fill) and in compliance with our plans and 310 CMR 15.000. The installer representative (**Karls Excavating**). Our inspection noted that the system was built properly, in accordance with the state regulations and our plans. The contractor was requested to have sufficient breakout soil on site and properly cover the system according to our plans and may backfill the system after review by local Health Department representatives.

Sincerely,

**Cold Spring Environmental Consultants, Inc.**

  
Alan E. Weiss, M.S., L.S.P.  
President  
Principal Hydrogeologist  
Licensed Site Professional #6442  
Registered Sanitarian #933

11-12-08  
Copies given to  
Mr. Poli of  
As-Built

Cold Spring Environmental  
350 Old Enfield Road  
Belchertown, Ma. 01007

413-323-5957, phone  
413-323-4916, fax

*\*As built Attached,*

1900  
1901  
1902



# AMHERST *Massachusetts*

AMHERST HEALTH DEPARTMENT, 70 BOLTWOOD WALK, AMHERST, MA 01002  
(413) 256-4077

(413) 256-4033 ENVIRONMENTAL HEALTH SERVICES  
(413) 256-4053 (FAX)

## SUB-GRADE INSPECTION

Location: Mr. Poli

Property Owner: 74 Wildflower Ln.

I certify that I have inspected the excavation to sub-grade of the proposed septic system leaching area prior placement of any fill of stone, or construction of any portion of the system.

I further certify that:

1. All 'A' and 'B' horizon soils (topsoils and subsoils) were removed in the area of the system.
2. There was no evidence of ground water in the excavation.
3. There was no evidence of "mottles" that would be in conflict with the findings of the deep hole soil profile.
4. That the excavation was accomplished to the proper depth and in conformance with the approved plans.

Alan Weiss  
 COLD SPRING  
 ENVIRONMENTAL, INC.  
 Designers Name  
 330 OLD ENFIELD RD.  
 BELCHERTOWN, MA 01007

[Signature]  
 Designers Signature



10/27/08

Street Address

Town, State, Zip Code

413-323-5957  
 Telephone Number



THE UNIVERSITY OF CHICAGO  
LIBRARY  
540 EAST 57TH STREET  
CHICAGO, ILL. 60637

**NOT AN ACTUAL SURVEY!!**  
 LINES DRAWN FOR SEPTIC  
 LOCATION PURPOSES ONLY!

**AS BUILT**  
 10.27.2008  
**MAP 21D LOT 87**  
**SCALE: 1"=30'**  
**38,333± Sq. Ft.**  
**0.880± Ac.**

- WETLAND I**  
**NOTE: All fa**  
*(free*
1. NO ALTERA  
ON THE DO
  2. SEDIMENT/  
MANOR AS
  3. NOTIFY CO  
START OF (
  4. AS SOON A  
WITH GRAS  
OF SITE WC
  5. SILT FENCE  
CONTROL F
  6. REGRADE \

- GRAVIT**  
**MAINTA**
- 1.) HAVE
  - 2.) MAINT  
OR SII
  - 3.) DO NC  
SHRUI
  - 4.) USE C
  - 5.) CLEAN



**LARKSPUR DRIVE**

**WILDFLOWER DRIVE**

